Dear Sir or Madam

The REM401 I/O card, mounted in the Propulsion Control Unit cabinet for the AT2000 remote control system, has been discontinued. This means that it is no longer possible to service or replace the REM401 I/O cards in the cabinet. To prevent any discomfort for you in relation to breakdowns or bad performance from the REM401, we recommend you to take action now and order our upgrade package.

The upgrade package consists of a new I/O card called BXM2200 that will replace the former REM401 I/O card. Unfortunately, this is not a plug-and-play solution, so we also need to change the CPU module. Besides the CPU and the new BXM2200 I/O card, we also make sure that the connections are working properly. In conclusion, we also make sure the software is adapted for your specific propulsion plant.

Installing the new REM401 upgrade package requires a superintendent with expert knowledge of the AT2000 system. So, if you have any maintenance planed in the near future, it would be preferable to order the REM401 upgrade package and get the super-intendent to install this when already onboard.

If you have any questions, are interested in ordering, or have just general interest in the REM401 upgrade, please contact our PrimeServ Retrofit department by e-mail to:
PrimeServ-FRH-Retrofit@man-es.com.

Yours faithfully

Michael Petersen
Vice President
PrimeServ Denmark

Jens Seeberg
Senior Manager
Retrofit & Upgrade